

Upper Section of Stillmeadow Drive Stream Restoration Project: Existing Conditions



Photo 1: Twelve foot high eroded bank that is beginning to undercut.



Photo 2: Erosion has caused large trees to fall within the channel; resulting in channel blockages and debris jams.

Middle Section of Stillmeadow Drive Stream Restoration Project: Existing Conditions



Photo 3: Lateral Bank Erosion



Photo 4: Failed riprap stabilization



Photo 5: Gabion basket bank protection



Photo 6: Tree failure due to lateral erosion

Lower Section of Stillmeadow Drive Stream Restoration Project: Existing Conditions



Photo 7: Sediment deposition and tree failure



Photo 8: Stable channel at downstream end of project



Photo 9: Existing 33-inch concrete culvert beneath Foster Knoll Drive

Roxbury Court Project Site: Existing Conditions



Photo 10: Electrical Transmission Right-of-Way



Photo 11: Dense vegetation at project site



Photo 12: Existing inlet near intersection of Roxbury Court and Blackburn Court